

Fig. 6.3 The Glass Box.

remains stationary. The hinge lines of the glass box are known as folding lines.

The positions of these six planes, after they

have been revolved, are shown in Fig. 6.4. Carefully identify each of these planes and corresponding views with its original position in the

Fig. 6.4 The Glass Box Unfolded.

